ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W0976, W0988, W1479, W1469, W0978, W1441, W0980, W

Street Name
NA, Rainbow Line 2nd Main Rd, 10th Crs, 2nd Crs, Junnasandra Village 14th Crs, 6th Crs, 9th Crs

Significant Landmark
bharathnagara balloon factory

Segment No.
6/C-W0976/S020722

Total Length (m)
500.93

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	59.93	77.629913	13.050567	77.629980	13.051104	W0976	DEAD END
2	58.96	77.629704	13.050594	77.629763	13.051124	W0976	DEAD END
3	58.82	77.629515	13.050616	77.629580	13.051144	W0976	DEAD END
4	40.93	77.629156	13.050640	77.629206	13.051007	W0976	DEAD END
5	58.11	77.628570	13.050248	77.629067	13.050052	W1451	SWD
6	27.89	77.628696	13.050471	77.628933	13.050375	W1441	SWD
7	49.24	77.629049	13.050566	77.628870	13.050157	W0976	W0982
8	74.23	77.629753	13.050509	77.629479	13.049894	W0976	W0988
9	72.82	77.629972	13.050475	77.629713	13.049868	W0976	W0988

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to road & drain at bharathnagara balloon factory in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
4000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Road

Other Work Type

Tender
Tender

Work Details
Improvements to road & drain at bharathnagara balloon factory in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Job No. / Work Code
006-15-000040

Work Order No.
BBMP/EE/BTP/WO/342/2015-16

Work Order Date
30/03/2016

Period of Extention
90 DAYS

Defect Liability Period From

Defect Liability Period To

Multiple road involved with the same Job No/ Work Code #

30/03/2016	29/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Y.B.RAMESH		0.00
Phone No.	**E-Mail ID**	
9611118200		

Field Inspection Details

Number of Trees	Any Other Information	Name
3		KRISHNAPPA
Date of Inspection	**Remarks**	
12/07/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0976, W0988, W1479, W1469,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0976, W0988, W1479, W1469,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	12/07/2016	11/08/2016	COMPLETED
SE	VASU K M	12/07/2016	11/08/2016	COMPLETED
EE	YARAPPA REDDY	12/07/2016	11/08/2016	COMPLETED
AEE	J N LOKESH	12/07/2016	11/08/2016	COMPLETED
AE	KRISHNAPPA	12/07/2016	11/08/2016	COMPLETED
AE	KRISHNAPPA	12/07/2016	11/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0976, W0988, W1479, W1469,